ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalkunte
Street ID	**Street Name**	**Significant Landmark**
W0004, W0006, W0008	NA	NAVYA LYT
Segment No.	**Total Length (m)**	
14/S-W0232/S075915	160.39	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	70.18	77.515659	13.071638	77.516622	13.071243	W0037	W0019
2	50.69	77.515487	13.071410	77.516555	13.070945	W0037	W0020
3	40.52	77.515930	13.071834	77.516815	13.071460	W0037	W0020

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to roads and drains at navya lyt	2000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road and drain	
Tender	**Work Details**	**Job No. / Work Code**
Not Tender	Road and drain workk	014-17-000033
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/DD/WO/24/2017-2018	21/06/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
21/06/2017	20/09/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9743188999		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunath

Date of Inspection	Remarks
05/06/2017	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	VIJAY KUMAR	05/06/2017	05/07/2017	COMPLETED
EE	SHESHADRI	05/06/2017	05/07/2017	COMPLETED
AEE	RANGASWAMY	05/06/2017	05/07/2017	COMPLETED
AE	MANJUNATH	05/06/2017	05/07/2017	COMPLETED
AE	MANJUNATH	05/06/2017	05/07/2017	COMPLETED

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalkunte **Street ID:** W0008